

Protecting the Common Waters of the Great Lakes Basin Through Public Trust Solutions

August 25, 2016

Ms. Heidi Grether Director Michigan Department of Environmental Quality P.O. Box 30458 Lansing, Michigan 48909-7958

Ms. Kim Fish Acting Chief Water Resources Division Michigan Department of Environmental Quality P.O. Box 30458 Lansing, Michigan 48909-7958

Mr. James Milne, Env. Manager Mr. Thomas Graf, Env. Specialist Great Lakes Submerged Lands Unit P.O. Box 30458 Lansing, Michigan 48909-7958

Mr. Scott Rasmusson Great Lakes Shorelands Unit Gaylord District Office Michigan Department of Environmental Quality 2100 West M-32 Gaylord, Michigan 49735

VIA ELECTRONIC SUBMISSION

RE: SUPPLEMENTAL PUBLIC COMMENTS AND TECHNICAL NOTE ON THE JOINT APPLICATION OF ENBRIDGE ENERGY TO OCCUPY GREAT LAKES BOTTOMLANDS FOR ANCHORING SUPPORTS TO TRANSPORT CRUDE OIL IN LINE 5 PIPELINES IN THE STRAITS OF MACKINAC AND LAKE MICHIGAN [NO. 2HB-VGKO-35JE]

Dear Michigan Department of Environmental Quality Director Grether, Officials, and Staff:

For Love of Water ("FLOW") is submitting this supplemental public comment and technical note related to Enbridge Energy's joint application to Michigan Department of Environmental Quality ("MDEQ") and the U.S. Army Corps of Engineers ("Corps") that requests authorization for additional anchoring supports to transport crude oil in Line 5 pipelines in the Straits of Mackinac and Lake Michigan.

As indicated in our initial public comments, this case presents a high risk of substantial likely impairment and safety concerns about the integrity of Enbridge's Line 5 twin underwater pipelines, as well as the mandatory state legal duties to protect health, safety, and welfare of the Great Lakes. The attached Technical Note prepared by Dr. Edward Timm – *"Regarding Enbridge Line 5 Non-Compliance with 1953 Easement Requirements, A Mechanistic Analysis of Straits Pipeline Washout Phenomena"* – reinforces this conclusion and raises grave and inherent structural stability questions resulting from the pipeline design error by Bechtel, Inc. in 1953. Specifically, this technical note concludes that Enbridge cannot safely comply with the easement's 75-foot support requirement using biennial underwater inspection methods, because no predictive current model exists to reliably predict future erosion or "washouts" along the pipeline following extreme weather events in the Straits of Mackinac.

Given Enbridge's history of repeated span violations coupled with the unpredictable Straits currents, it is impossible for Enbridge to prevent future violations. As a result, Enbridge's continued transport of crude oil in Line 5 in the Straits poses an unacceptable level of harm to the Great Lakes waters and aquatic resources as protected by the Great Lakes Submerged Lands Act ("GLSLA"), public trust, and the Michigan Environmental Protection Act ("MEPA"). This is especially the case because feasible and prudent alternatives currently exist to allow the continued transport of crude oil *around* the Great Lakes.

Based on this critical technical information about the safety of the Straits section and our prior submission on legal requirements, we recommend that the MDEQ exercise heightened scrutiny and take immediate steps to minimize the risk Line 5 poses to protect the health, safety, and welfare of the public. To this end, we urge the MDEQ to take either course of action:

1. immediately terminate the transport of crude oil in Line 5 at the Straits pending a comprehensive agency review of impacts, risks, and alternatives;

or

- 2. issue an emergency "conditional permit" under section MCL 324.32514(2) of the GLSLA to install the four identified anchors to address the violation of the 1953 easement, subject to specific conditions that impose interim measures "to protect property or public health, safety, or welfare" and public trust in the Great Lakes. The MDEQ should consider including the recommendations of Dr. Timm in the attached Technical Note referenced above:
  - (a) Clean pipelines of all marine growth (biofouling) and conduct full external inspection to evaluate the extent of external corrosion and condition of the protective coating.
  - (b) Calculate the weight, drag, and curvature of pipelines due to the biofouling from mussels, algae and silt that were not anticipated as part of the original engineering design.

- (c) Install multiple current profilers on the twin pipelines to measure the maximum current velocities and compare this data to the original current design calculations in the Straits (2.26 mph maximum)
- (d) Hire an independent third-party contractor to recalculate the safety margins of the pipelines' unsupported length requirements given unanticipated powerful underwater currents, historic events, and biofouling stresses.
- (e) Install a continuous weather and current monitoring system that shuts down oil transport in Line 5 during extreme weather events in the Straits of Mackinac.

In addition, it is emphasized that any emergency conditional permit issued pending full review (as required by the GLSLA, the MEPA, and public trust law) must inform Enbridge that this temporary authorization (1) requires immediate action to protect the public health, safety, and general welfare, and the air, water, and natural resources and public trust in those resources; (2) does not constitute satisfaction or compliance with the requirements of the GLSLA or other applicable laws and regulations; and (3) does not otherwise bind the MDEQ or state in any manner regarding the requested permits for the occupancy and activities in question. In sum, a comprehensive review is required because Enbridge cannot prevent the high risk of harm and potential impacts from a ruptured pipeline, and alternative pipeline design capacity and routes exist.

We appreciate the department's efforts to protect the public interest in the Great Lakes and to comply with these laws and the public trust duties and principles that apply. Thank you.

Sincerely yours,

Janos

James M. Olson President

Jin Kinhund

Elizabeth R. Kirkwood Executive Director

 CC: Charles Simon, Chief, Regulatory Office, Corps Detroit District Kerrie Kuhn, Chief, Permits, Corps Detroit District Michigan Governor Rick Snyder Michigan Attorney General Bill Schuette MDNR Director Keith Creagh U.S. Senator and Hon. Gary Peters U.S. Senator and Hon. Debbie Stabenow

## Technical Note

## <u>Regarding Enbridge Line 5 Non-Compliance with 1953 Easement Requirements</u> <u>A Mechanistic Analysis of Straits Pipeline Washout Phenomena</u>

## Edward E. Timm, PhD, PE 5785 Deer Run Trail, Harbor Springs MI 49740 EdTimm@Gmail.com

The two legs of Enbridge's Line 5 that lie on the bottom of the Straits of Mackinac are constructed of very heavy 20" pipe and must be supported to prevent collapse due to gravitational force. A review of the original design calculations<sup>1</sup> conducted by famed structural engineer, Dr. Mario G. Salvadori, approved the design analysis made by Bechtel Inc. personnel and set limits on maximum unsupported span lengths. Based on both Bechtel's original design and Dr. Salvadori's calculations, the State of Michigan set a maximum unsupported span distance of 75 feet when it granted the easement<sup>2</sup> under the Straits. Dr. Salvadori additionally noted in his report that any unsupported span over 140 feet was dangerous and that the pipe should not be allowed to sag to a radius of curvature of less than 1750 feet during construction. These values were based on information provided to Dr. Salvatore and assumed that the maximum current under the Straits was 1.96 knots (2.26 mph). These calculations did not anticipate or include loads on the pipe due to biofouling and the mussel growth that started after the opening of the St. Lawrence Seaway in 1958. A review of these documents also reveals that the possibility that currents would erode the supporting soil under the pipe leading to 'washouts" was not considered.

When the Straits sections of Line 5 were designed by Bechtel engineers, the engineering science of underwater pipeline design was in its infancy. Many design efforts involving short river crossings where the pipe is buried in the river bottom had proven successful but there was little experience with longer crossings where the pipe was placed on the bottom of a body of water without burial. As the offshore oil industry developed in the 1960's the need for such pipelines drove engineering understanding and the problem with currents washing away the bottomlands that support an underwater pipeline was recognized. In retrospect, the mis-estimation of the magnitude of currents under the Straits coupled with the lack of understanding about the soil entrainment processes that cause washouts can be seen as a fatal flaw in the design of the Line 5 Straits crossing.

Although much has been published about the problem with washouts under Line 5 with resultant lack of support and easement violations, it does not appear that the mechanism causing this problem has been previously elucidated. Washouts occur because of currents that are fast enough to entrain soil particles and move them away from beneath the pipe. Figure 1, calculated from the Levillain<sup>3</sup> equation, illustrates the extremely nonlinear nature of the soil entrainment process. This figure shows that at currents below the design maximum of 2.26 mph no soil particles larger than 0.5mm can be entrained. This velocity is sufficient to entrain silt and small sand particles but is not capable of moving most soil particles. Because the Levillain equation is highly nonlinear, current speeds greater than this value have a disproportional impact on the size of soil particles that can be entrained and transported. A three mph current will entrain particles with diameters on the scale of a millimeter which includes typical lake bottom sand and a six mph current can transport small rocks with diameters on the order of one half inch. This knowledge leads to the conclusion that pipeline washouts occur during events that cause extreme currents which are most likely found in turbulent eddy flows resulting from exceptional weather events across the Great Lakes Basin.

During its 63-year lifetime, the Straits sections of Line 5 have been consistently out of compliance with the easement's 75 foot maximum unsupported span requirement. Table 1, taken from copies of the "as built" drawings of the two Straits legs of Line 5 updated through the 1979 underwater inspection<sup>4,5</sup> shows a total of 17 spans that exceed the 75 foot maximum unsupported span distance and three spans that exceed the 140 foot structural damage threshold. Table 2, taken from another document filed by Enbridge at the request of the

Michigan Attorney General under the terms of the 1953 easement,<sup>6</sup> outlines the numerous campaigns undertaken from 1962 through 2012 to inspect and add support to the pipes. This information shows a lack of urgency on Enbridge's part to insure that Line 5 is both safe and complies with applicable language in the 1953 easement. In spite of all the non-compliances shown in Table 1 which was current as of January, 1980, Table 2 shows that no action was taken by Enbridge until 1987 to remedy this dangerous situation. In 1987, Enbridge began campaigns to insure adequate support under line 5, but, as can be seen from Table 2, the 1987 effort only added support to seven unsupported spans out of the seventeen noncompliant spans that were documented in the 1980 drawings. This 1987 effort certainly did not bring Line 5 into compliance with the easement.

Beginning in 2001 and continuing today, Enbridge has made efforts to add modern screw anchor supports to Line 5 to bring it into compliance with the easement and, more importantly, prevent damage to the line. As can be seen from Table 2, a total of 106 supports were added to Line 5 through 2012. A 2014 campaign by Enbridge found 40 spans that violated easement requirements. Following this campaign Enbridge stated that there were no unsupported spans over 75 feet and the average unsupported span was 50 feet. This calculates to a total supported distance of 1.38 miles out of a total exposed distance of 4.4 miles (2.3 miles West leg, 2.1 miles East leg) which means only about 31% of the pipe has discrete supports and is not subject to washout. A recent (7/2016) underwater survey of Line 5 has found four more spans that are out of compliance with the easement and eighteen spans that Enbridge plans to support proactively to prevent future non-compliance. This information is documented in a construction permit application to the State filed in August, 2016 with a planned work start date in September, 2016. The ongoing nature of washouts under Line 5 with resulting easement non-compliances demonstrates conclusively that strong currents and a shifting bottom under the Straits requires continuous vigilance to prevent excessive spans that could result in collapse of Line 5. A careful analysis of all the documentation publicly available about this issue leads to the conclusion that the Straits segments of Line 5 never met the easement support and curvature requirements as constructed in 1953 and have been consistently and sometimes dangerously out of compliance since that date. It may be that Enbridge's support efforts have brought the line into compliance with easement requirements for brief periods but it is certain that easement requirements have not been met for the great majority of its life to date.

An analysis of the current data taken in the Straits by Saylor and Miller in 1991<sup>7</sup> shows that the original designers of Line 5 seriously underestimated the strength of the currents impacting the structure. This data shows that 15 minute average currents near Line 5 can exceed the design basis for several hours each year and that at some times the currents exceed 4 mph. It is probable that Line 5 washouts are caused by local turbulent eddies with peak velocities over 6 mph that occur infrequently likely during seiche inducing Derecho events or other extreme weather events. Due to the limited data available about extreme currents under the Straits and the probabilistic nature of the washout process, it is very difficult to predict when and where washouts will occur. Additionally, because of both marine fouling and current loadings well beyond the design basis, it is likely that the original stress calculations that resulted in the 75 foot maximum unsupported span requirement underestimate stresses in the pipe and the 75 foot requirement no longer results in the safety margins originally contemplated in the 1953 easement agreement. These errors also affect the calculation that predicts severe consequences should an unsupported span over 140 feet develop. Given currents above the design basis and severe biofouling, the stresses predicted to occur at a 140 foot span are underestimated and severe consequences may occur at unsupported spans less than this length.

The finding that Line 5 needs more supports that resulted from Enbridge's 2016 underwater inspection and resultant construction permit application is, once again, an admission that Enbridge has consistently violated the easement allowing construction of Line 5. Apparently, after the 2014 support campaign by Enbridge, assurances were given to the State of Michigan that, in the future, no further easement non-compliances would occur. The fact that four such non-compliances were found and eighteen more supports are required to prevent potential future non-compliances has called into question Enbridge's assurances regarding their engineering competence and ability to comply. In an August 3, 2016 letter, Michigan's Attorney General, Bill Schuette<sup>8</sup>, notified Enbridge that, under the terms of the easement, they had to provide information about their ongoing inspection and repair program. Quoting from this letter:

"First, please provide as soon as possible, and in any event within 14 days of this letter, the results of the most recent underwater inspection of the Straits Pipelines in 2016. This includes a detailed description of the methods used to conduct the inspection, as well as the findings regarding pipeline support locations, span lengths observed, and changes to the conditions reported in 2014 that have led to the current situation where the four spans now exceed 75 feet. Specifically, please explain why and how the span lengths Enbridge represented existed in 2014 are now missing in those locations.

Second, please provide, within 14 days from this letter: (a) a detailed description of the predictive maintenance model that Enbridge relied upon and referred to in its November, 2014 letter; (b) a detailed explanation of how and why that model failed; and (c) a new span monitoring and preventative maintenance plan to ensure future and continuing compliance with the Easement pipeline support requirement. That plan should include, as needed, increased inspection frequency and proactive pipeline support repair, installation and replacement to prevent any spans greater than 75 feet before they occur."

Based on my analysis of current data and knowledge of hydrodynamics, it is probable that a model to predict future washouts that does not take into account current data will not be reliable. As shown by Anderson and Schwab<sup>9</sup>, the oscillating flows through the Straits are driven by atmospheric pressure differences and reach extreme values during severe weather events like a Derecho induced seiche. Without taking this information into account, it is likely that washouts can occur that will go undetected by Enbridge's two year underwater survey schedule. Because a truly extreme weather event could produce a washout that exceeds the 140 foot limit for structural damage to Line 5, the risk of a rupture in Line 5 in its current condition cannot be said to be negligible. This observation raises the question of what action should be taken by the State of Michigan to assure the safety of the Straits sections of Line 5 given Enbridge's continuous inability to comply with easement support requirements since before 1975.

Allowing Enbridge's current process of bi-annual underwater inspection followed by repair to continue under these circumstances guarantees that the Straits sections of Line 5 will not be in compliance with easement requirements most of the time. Indeed, there is a finite possibility that the probabilistic nature of the washout process will result in a dangerously long unsupported span that could go undetected for over a year. This approach seems neither reasonable nor prudent since a rupture and large oil spill in the Straits would be incomprehensibly damaging to Michigan's economy and ecology. If the obvious remedy of shutting down this pipeline is judged to be too extreme based on economic concerns, it would be reasonable and prudent to take an approach that incorporates the technical arguments made in this document to reduce risk.

Since routinely scheduled (2 year) underwater inspections cannot guarantee the level of reliability that may be necessary in such a critical waterway, an event triggered approach may be useful. Real time monitoring of weather events and currents in the most vulnerable areas of the pipeline in conjunction with a Straits flow model like that of Anderson and Schwab could provide the data necessary to determine when currents reach values that threaten pipeline stability. When such a condition is reached, it would be prudent to either shut down Line 5 or restrict it to non-oil cargo until an underwater inspection could be made. These event triggered inspections along with ameliorative action would provide a level of safety unobtainable through regular inspections at reasonable cost. This approach is used in many other safety critical situations with good results. For example, commercial airliners continually record flight information and any event that causes an airplane to exceed preset limits triggers a thorough inspection, review and repair/replace decision by the operator. This approach could be used to make sure the frequent, unpredicted washouts that plague the Straits sections of Line 5 would not result in rupture when pressurized with crude oil during an extreme current event.




Figure 1. Soil Particle Entrainment Velocity as a Function of Underwater Current Velocity

1.	Data taken from Lake	head Pipeline Comp	any, Inc drawings relea	used by Michigan Attor	ney General	
	Drawing originally dat					
	Drawing updated thro					
	Unsupported spans o					
5.	Unsupported spans o	ver 140 feet were cal	culated to be dangerou	us to line integrity by or	iginal designers at Bechtel	
	Summary of non-Corr	pliant Lincupported S	nans as of 1090	1		
	Summary of non-Con	ipilarii Urisupporteu 3	paris as or 1960			
	Location	Spans > 75 feet	Spans > 140 feet			
	West Leg	10	3			
	East Leg	7	0			
Leg S	Spans and Supports					
	Feature Description	Approximate Bechtel Chainage	Approximate Depth	Unsupported span Length (feet)	Notes	
	Beginning	5140	65	Lengin (leet)	Notes	
	Span	6800	105	60		
	Span	7000	130	70		
	Clay Pile	7050	135			
	Span	7100	135	30		
	Span Span	7300 7400	165 180	60 100		
	Clay Pile	7400	210	100	Evidence of strong current action	
	Span	7600	240	150	Two sets of grout filled bags placed in 1978 to support span.	
	Note	8000			Area of many large rocks and boulders, well silted	
	Clay Pile	8100	240			
	Span	8300	235	60		
	Clay Pile Span	8560 8600	242 245	80		
	Span Span	8700	245	70		-
	Span	8800	240	50		
	Span	8900	225	85		
	Span	9100	220	50		
	Span	9300	205	60		
	Span Burial	9500 9650	180 175	110	Pipe embedded 6-8 feet	
	Span	9800	180	80		
	Span	10000	185	70		
	Note	10300	170		6" triangular pieces of coating chipped off during 1978 construction	
	Span	10800	170	150	Two details on drawing showing pipe sideways movement and pipe unsupported in tre	nch
	Clay Pile	11200	130	100		
	Span Span	11600 11800	130 135	160		
	Clay Pile	12000	135	100		
	Span	12250	135	70		
	Clay Pile	12350	135			
	Span	12450	135	40		
	Span	12700	130	40		
	Clay Pile	12900	130			_
	Clay Pile Span	13100 13200	130 130	60		
	Note	13350	130	00	Cable mark on pipe, no damage	
	Span	13500	130	90		
	Span	13900	95	35		
	Clay Pile	14050	95	50		
	Span	14300	95	50	Two small clay piles appear to have	
	Span Span	14400 14500	95 95	50 20	from one original	
	Span	15200	80	40	Several small clay piles appear to have	
	Span	15600	75	40	been used to support pipe in area of non	
	Span	16400	75	10		
	End	17260	65			
00.5	Spans and Supports					
.eg o	spans and Supports					
		Approximate		Unsupported span		
	Feature Description		Approximate Depth	Length (feet)	Notes	
	Beginning	5040	65			
	Span	5510	70	80	Two sets of grout bags added in 1978 to	
	Span Span	5650 6000	70 115	70 70	suppoirt spans	
	Note	6350	160	10	Large Rock	
	Note	6400	160		Gravel Ridge	
	Span	6450	160	70		
	Span	7060	210	80	Evidence of strong current action	
	Clay Pile	7500	220	80		
	Span	7720 8050	220 225	80		
		0000		80		
	Trench	8120	2.37			
		8120 8160	232 232			
	Trench Span Clay Pile Span	8160 8200	232 232	90		
	Trench Span Clay Pile Span Span	8160 8200 8510	232 232 190	90		
	Trench Span Clay Pile Span Span Span	8160 8200 8510 8740	232 232 190 165	90 60		
	Trench Span Clay Pile Span Span Span Span	8160 8200 8510 8740 8880	232 232 190 165 140	90 60 70		
	Trench Span Clay Pile Span Span Span	8160 8200 8510 8740	232 232 190 165	90 60		
	Trench Span Clay Pile Span Span Span Span Span Span	8160 8200 8510 8740 8880 8950	232 232 190 165 140 130	90 60 70		
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Trench	8160 8200 8510 8740 8880 8950 9000 9210 9270	232 232 190 165 140 130 130 130	90 60 70		
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Trench Clay Pile	8160 8200 8510 8740 8880 8950 9000 9210 9270 9590	232 232 190 165 140 130 130 130 130 130 140	90 60 70 60		
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span	8160 8200 8510 8740 8880 9000 9210 9270 9270 9590 9600	232 232 190 165 140 130 130 130 130 140 140	90 60 70	Image: sector	
	Trench Span Clay Pile Span Span Span Trench Clay Pile Trench Clay Pile Span Trench	8160 8200 8510 8740 8880 8950 9000 9210 9270 9590 9600 9800	232 232 190 165 140 130 130 130 130 130 130 140 140	90 60 70 60	Image: second	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Trench Clay Pile	8160 8200 8510 8740 8880 9900 9210 9270 9590 9600 9800 9990	232 232 190 165 140 130 130 130 140 140 140 140	90 60 70 60 50	Image: sector	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Trench Clay Pile Span	8160 8200 8510 8740 98880 9900 9210 9270 9590 9600 9800 9990 10450	232 190 165 140 130 130 130 130 140 140 140 140 140 120	90 60 70 60 50 70	Image: sector	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Trench Clay Pile	8160 8200 8510 8740 8880 9900 9210 9270 9590 9600 9800 9990	232 232 190 165 140 130 130 130 140 140 140 140	90 60 70 60 50	Image: sector	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span	8160 8200 8510 8740 8880 9000 9220 9590 9600 9800 9800 9990 10450 10740 10550 11400	232 232 190 165 140 130 130 130 140 140 140 140 140 140 140 140 140 1595	90 60 70 60 50 50 70 60 70	Image: sector	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile	8160 8200 8510 8740 8880 9900 9210 9270 9590 9600 9800 9990 10740 10750 11400 11930	232 232 190 165 140 130 130 130 140 140 140 140 140 140 110 105 95 100	90 60 70 60 50 70 60	Span well anchored	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile	8160 8200 8510 8740 8880 9900 9210 9270 9590 9600 9800 9990 10450 10450 10740 10950 11400 11930	232 232 190 165 140 130 130 130 130 140 140 140 140 140 140 120 110 5 95 100 95	90 60 70 60 50 50 70 60 70 90	Span well anchored	
	Trench Span Clay Pile Span Span Span Span Clay Pile Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Span	8160 8200 8510 8740 8880 8950 9270 9270 9590 9600 9800 9990 10740 10450 11400 11930 12150 12400	232 232 195 165 140 130 130 130 140 140 140 140 140 140 140 110 55 100 95 100	90 60 70 60 50 50 70 60 70	Span well anchored	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile	8160 8200 8510 8740 8880 9900 9210 9590 9600 9800 9800 9990 10740 10750 11400 11930 12150 12500	232 232 190 165 140 130 130 130 140 140 140 140 140 140 140 140 15 95 100 95 105	90 60 70 60 50 70 60 70 90 80	Span well anchored         Image: Span well anchored         Image: Span well anchored         Image: Span well anchored	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Span Clay Pile Span	8160 8200 8510 8740 8880 8950 9270 9590 9800 9800 9990 10450 10450 11400 11130 12150 12400 13300	232 232 190 165 140 130 130 130 140 140 140 140 140 140 140 140 15 95 105 105 105 90	90 60 70 60 50 50 70 60 70 90 80 80	Span well anchored	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile	8160 8200 8510 8740 8880 9900 9210 9590 9600 9800 9800 9990 10740 10750 11400 11930 12150 12500	232 232 190 165 140 130 130 130 140 140 140 140 140 140 140 140 15 95 100 95 105	90 60 70 60 50 70 60 70 90 80	Span well anchored	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Trench Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span Clay Pile Span	8160 8200 8510 8740 8880 8950 9000 9210 9270 9590 9600 9800 9990 10740 10450 11400 11930 12150 12400 123300 13300 13600 14480	232 232 190 165 140 130 130 130 130 140 140 140 140 140 140 140 140 140 14	90 60 70 60 50 50 70 60 70 90 80 80 70 50	Image: second	
	Trench Span Clay Pile Span Span Span Span Trench Clay Pile Span Trench Clay Pile Span Clay Pile	8160 8200 8510 8740 8880 8950 9000 9270 9590 9600 9800 9990 10450 10740 10740 10750 11400 12150 12450 12500 13300 13600	232 232 190 165 140 130 130 130 140 140 140 140 140 140 140 15 95 100 95 105 105 90 80 70	90 60 70 60 50 50 70 60 70 90 80 80 80 70	Span well anchored Pipe is 5 to 6 feet off bottom in this area	

Year of ROV Inspection	Follow up Actions (Anchor Support Installation)	Type of Support Installed
1963	None	
1972	None	
1975	3	Grout Bags
1979	None	
1982	None	
1987	7	Grout Bags
1989	None	
1990	None	
1992	6	Grout Bags
1997	None	
2001	8	Grout Bags and mechanical support
2003	16	Mechanical Screw Anchors
2004	16	Mechanical Screw Anchors
2005	14	Mechanical Screw Anchors
2006	12	Mechanical Screw Anchors
2007	None	
2010	7	Mechanical Screw Anchors
2012	17	Mechanical Screw Anchors

Table 2 ROV Inspection and Span Support Installation History of Line 5 Straits of Mackinac

<sup>&</sup>lt;sup>1</sup> "Report on the Structural Analysis of the Subaqueous Crossing of the Mackinac Straits", Salvadori, Mario G., PE, Department of Civil Engineering, Columbia University, New York 27, NY, January 19, 1953.

Also released by the State of Michigan as: "Engineering and Construction Considerations for the Mackinac Pipeline Company's Crossing of the Straits of Mackinac" and "Report on the Structural Analysis of the Subaqueous Crossing of the Mackinac Straits," submitted by Mackinac Pipeline Company/Lakehead Pipeline Company to the Michigan Department of Conservation, January, 1953 http://www.michigan.gov/documents/deq/Appendix\_A.2\_493980\_7.pdf

<sup>&</sup>lt;sup>2</sup> "Straits of Mackinac Pipeline Easement", Conservation Commission of the State of Michigan, April 23, 1953.

<sup>&</sup>lt;sup>3</sup> "Critical Soil Particle Entrainment Velocity", <u>Stability and Operation of Jackups</u>, Chapter 4.5.1.2, pages 222-223, Pierre Le Tirant and Christian Perol, Editors, Design Guides for Offshore Structures, Editions TECHNIP, Paris, France 1993.

<sup>&</sup>lt;sup>4</sup> "East Line Profile, Mackinaw Straits Crossing, Underwater Inspection", Lakehead Pipeline Company, Inc., 4/14/64, Updated 1972, 1975 and 1979, http://www.michigan.gov/documents/ag/164-00-1\_700-10483-01\_523921\_7.pdf?20160819195501

<sup>&</sup>lt;sup>5</sup> "West Line Profile, Mackinaw Straits Crossing, Underwater Inspection", Lakehead Pipeline Company, Inc., 4/14/64, Updated 1972, 1975 and 1979, http://www.michigan.gov/documents/ag/164-00-1\_700-10483-01\_523922\_7.pdf?20160819195501

<sup>&</sup>lt;sup>6</sup> "Table 2 ROV Inspection and Span Support Installation History of Line 5, Straits of Mackinac", Appendix 2B, Table 2, p. 4 (document Appendix\_B4\_493991\_7.pdf, MPP Task Force Record).

<sup>&</sup>lt;sup>7</sup> "Current flow through the Straits of Mackinac", James Saylor and Gerald Miller, Great Lakes Environmental Research Laboratory Ann Arbor, Michigan, Technical Report, 1991

<sup>&</sup>lt;sup>8</sup> "Re: *Enbridge Lakehead System Line 5 Pipelines at the Straits of Mackinac*", Letter from Michigan Attorney General Bill Schuette to Brad Shamla, Vice President U. S. Operations, Enbridge Energy Limited Partnership, August 3, 2016.

<sup>&</sup>lt;sup>9</sup> " Predicting the oscillating bi-directional exchange flow in the Straits of Mackinac", Eric J. Anderson and David J. Schwab, Journal of Great Lakes Research, December, 2013.